



#13001

# Grounding Kit

Be sure metal to metal contact is made for proper grounding.



No	Part Name	Qty
1	Grounding Screws	2
2	Wire Nuts	5
3	Terminal Ends	2
4	50' Braided Bare Copper Wire	1
5	3/32" Drill Bit	1



Make sure all machines are grounded with a 3 prong plug and that all duct & hose used to connect the collector to each machine are internally grounded.